

SOUTHWEST CORNER NORTHEAST QUARTER
SECTION 8, T. 6 S., R. 9 W.
2nd PRINCIPAL MERIDIAN

FOR NOTES ON CORNER HISTORY SEE REVERSE

A 3x3 grid of squares. The center square contains a circle with a solid black dot in its center. The other squares are empty.

2' Wide Ditch

6'

2-1/2" pipe is bent approximately 20" below grade; measurements to pipe were taken at 20" depth

Found RR Spike 3" Below Grade

1305.15'

9°5'14"

0°10'40"

1115.05'

1°33'52"

1296.67'

1321.29'

Found 1/2" Rebar 7" Below Grade

Found RR Spike Flush

Found Rebar w/Feldbusch Cap

Stevenson Station Road

Note: Angles and distances shown are calculated from traverse data; points shown may not be directly visible from the corner.

APPROVED BY:

DATE:

REFERENCED BY: D.DREES/G.F.BERRY

DATE: 5/13/03

APPROVED BY: P.JONES, RLS#9600016

DATE: 7/25/03

CORNER FILE CODE:
T6S-R9W-G-07